


Explosive drawing LPCM-1



Part list:

1. Temperature Control Box 2.Box Assembly 3.Thermal Insulation Board
4.Heating Element 5.Plate 6.Cable 7.Bottom cover 8.Oil Pan 9. Feet