


Explosive drawing LPCM-2



Part list:

1. Temperature Control Box
2. Box Assembly
3. Thermal Insulation Board
4. Heating Element
5. Plate
6. Cable
7. Bottom cover
8. Oil Pan
9. Feet